



Original post set 1820 by John Hendricks with witnesses: 11" beech S 16 E 18 links, 14" dogwood N 80 W 17 links per Marion County Atlas pg. 14. A survey by D.B. Hosbrook 9-2-1856 indicates no stone or witnesess per Franklin Township Legal Survey Book pg. 6. MCSO 1-7-57 called a stone. Fleener 7-22-69 called an iron pin found. Hancock County 5-20-77 called a brass plug and plate was set by them.Gries 11-10-87 called the same. Kiste 10-11-94 called a brass pin with octagnal plate. Excavated by Kiste 12-17-99 and a copper weld with octagonal plate was found 3" down. No stone or other monuments were found. Harrison set.

HC553403

REF.	DISTANCE	DESCRIPTION
1.	75.31'	PK nail NW PwP#1-681GA 14*up
2,	19.59'	PK nail NW PwP#6-681GA 12"up
3.	53.90'	Road nail S PwP#37-681GA 12"up
4.	18.85	NW corner of plastic corner fence post
5.	125.60	PK nail W PwP#14-681GB 12"up
6.	30.92'	NE corner of plastic corner fence post